

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 04/17/2012	3. Time Prepared 1700
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 04/12/12 – 0700, 04/19/12
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Matthew Haak		Situation Unit Leader	Houston, Texas
8. Activity Log			
Time	Major Events		
11:00	<p>Overflight Operational status:</p> <ul style="list-style-type: none"> <li>MP0.75 LDB, sheen observed along Talmadge Creek.</li> <li>MP1.0, sheen observed along Talmadge Creek at 16 Mile Rd.</li> <li>Frac-Tank City, footprint reduction continues.</li> <li>Frac-Tank City, truck observed emptying Soil Cells A &amp; B sump.</li> <li>Frac-Tank City, no decontamination activities observed.</li> <li>MP1.6 LDB Talmadge Creek, sheen observed.</li> <li>MP1.65 LDB Talmadge Creek, sheen observed.</li> <li>Walling tube installed within Talmadge Creek near the confluence.</li> <li>Walling tube buoy configuration up river from the confluence.</li> <li>Confluence, buoys removed.</li> <li>Observed C0.4 Boat Launch footprint reduction.</li> <li>Ceresco Dam, no sheen observed.</li> <li>Observed SORT Crew near MP6.0</li> <li>Observed MP8.4 LDB, last remaining SORT location.</li> <li>Observed MP9.10, area newly restored.</li> <li>Observed work continuing at Historic Bridge Park.</li> <li>MP22.75 RDB, RI crew observed.</li> <li>Boom located at MP30.8, no sheen observed.</li> <li>Boat launch E3, crew observed preparing to take water temperature readings.</li> <li>Morrow Lake Delta, no sheen observed.</li> <li>E4 Boom, no sheen observed.</li> <li>Observed Morrow Lake poling crew.</li> <li>Morrow Lake Dam, sediment moving over dam.</li> </ul>		
	Additional observations: None		
15:00	Return to ICP.		
9. Prepared by (Name and Position) Matthew Haak, Situation Unit Leader, USEPA-START			